Application No.: 10/736,665 Docket No.: 8734.275.00

Amendment filed on September 16, 2005 Reply to Office Action dated May 17, 2005

## **AMENDMENTS TO THE SPECIFICATION**

Please replace paragraph [0081] with the following amended paragraph:

[0081] It is necessary that the fixing device 41 for inserting the digitizer is adhered to the rear portion of the support main 13 of the LCM 10, and it is desirable that a double-faced tape 41c is used to stably fix the fixing device 41 for inserting the digitizer. That is, the entire device can be maintained to have a slim thickness by adhering the fixing device 41 for inserting the digitizer with the double-faced tape 41c as compared to fixing it with screws. And, while inserting the digitizer 40, the fixing device 41 for inserting the digitizer is fixed to the support main 13 and the digitizer can be installed safely.